



**Lift & Storage  
Systems, Inc.**

3580 Hoffman Road East  
White Bear Lake, MN  
55110 USA

[www.liftstore.com](http://www.liftstore.com)

[sales@liftstore.com](mailto:sales@liftstore.com)

800-825-4777



## Electrical Requirements for Overhead Lifts

Every section that has a motor on it needs:  
Two legs of 120 Volt consisting of one neutral leg and one ground leg.  
The receptacle must be a NEMA L14-20R.  
The receptacle to be located within four feet of the motor.

If you have questions please call:  
Jim L'Allier, Operations Director, 651-777-1554  
or  
Art Kroulik, Service Director, 651-288-7477